
SCHEMATIC DRAWING



PARTS LIST

No.	Description	Qty.	No.	Description	Qty.
1	Upper flang	1	21	#2 Woodruff key	1
2	Grinding wheel	1	22	609-2RZ Bearing	1
3	Lower flang	1	23	609-2RZ Bearing washer	1
4	Spindle	1	24	M4x8 screw	2
5	Wheel guard assembly	1	25	Rotor	1
5.1	Guard-adjusting lever	1	26	607-2RS Bearing	1
5.2	Wheel guard	1	27	ST4.2x16 screw	6
5.3	M6x10 screw	1	28	Switch push button	1
6	M4x14 screw	4	29	Switch push rod	1
7	Front cover	1	30	Switch transducer block	1
8	6001-2RZ Bearing	1	31	Column pin	1
9	Circlip	1	32	Right housing	1
11	#1 Woodruff key	1	33	Steel wire mesh	2
10	Big gear	1	34	Controller	1
12	φ11 Bearing circlip	1	35	Switch	1
13	HK0810 Bearing	1	36	Stator	1
14	φ5 Bearing circlip	1	37	Blushless label	1
15	ST4.2x18 screw	4	38	Speed control PCB	1
16	Gear Box	1	39	Left housing	1
17	Self-locking spring	1	40	Battery clip assembly	1
18	Self-locking button	1	41	Side handle	1
19	E-type circlip	1	42	Spanner	1
20	Small gear	1			